


PZL P 11c



1. Magnetic compass
2. Manifold pressure gauge
3. Airspeed indicator
4. Variometer
5. Tachometer
6. Engine temperature gauge
7. Fuel pressure gauge
8. Oil temperature gauge
9. Turn and bank indicator
10. Altimeter
11. Clock
12. Throttle



P11 ©J. Swiaton, <http://aircraftwalkaround.hobbyvista.com/pz11/pz11.htm>

