


# Republic P47 D-27 Thunderbolt



1. Undercarriage position indicator: green - down  
no light - in transition  
red - up
2. Clock
3. Magnetic compass
4. Artificial horizon
5. Airspeed indicator
6. Altimeter
7. Turn and bank indicator
8. Variometer
9. Magnetic compass
10. Manifold pressure gauge
11. Tachometer
12. Oil temperature (half), oil pressure (left), fuel pressure (right)
13. Accelerometer
14. Low fuel warning light
15. Fuel gauge
16. Oil temperature gauge
17. Throttle
18. Propeller pitch
19. Flaps lever



P47 (http://www.simplis.org/ hosted by Delasoft)

